

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2016

Submitted Date:

10/21/2016

Document Number:

666802654**FIELD INSPECTION FORM**
 Loc ID 335040 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299214	WELL	PR	03/27/2010	GW	045-17614	MILLER 33B-36-692	PR
299215	WELL	PR	03/27/2010	GW	045-17615	MILLER 33C-36-692	PR
299216	WELL	PR	04/13/2010	GW	045-17616	MILLER 44D-36-692	PR
299217	WELL	PR	04/13/2010	GW	045-17617	MILLER 43A-36-692	PR
299218	WELL	PR	04/28/2010	GW	045-17618	MILLER 43D-36-692	PR
299219	WELL	PR	04/28/2010	GW	045-17619	MILLER 43C-36-692	PR
299220	WELL	PR	04/28/2010	GW	045-17620	MILLER 33D-36-692	PR
299221	WELL	PR	04/26/2010	GW	045-17621	MILLER 42A-36-692	PR
299222	WELL	PR	03/27/2010	GW	045-17622	MILLER 43B-36-692	PR
299223	WELL	PR	04/26/2010	GW	045-17623	MILLER 32A-36-692	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 10

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 10

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	8	OTHER	STEEL AST		39.487081,-107.610772
Comment:					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity) 625bbbls

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299214	Type:	WELL	API Number:	045-17614	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299215	Type:	WELL	API Number:	045-17615	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299216	Type:	WELL	API Number:	045-17616	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299217	Type:	WELL	API Number:	045-17617	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299218	Type:	WELL	API Number:	045-17618	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299219	Type:	WELL	API Number:	045-17619	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299220	Type:	WELL	API Number:	045-17620	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	299221	Type:	WELL	API Number:	045-17621	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	299222	Type:	WELL	API Number:	045-17622	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	299223	Type:	WELL	API Number:	045-17623	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
Seeding	Pass					
		Check Dams	Pass			
		Gravel	Pass			
Gravel	Pass					
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802654	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982794">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3982794</a>