



Photo 1. View of the southern portion of the project area from the southeastern corner facing westward. Project area does not appear seeded. Vegetation shown in photo is Russian thistle (*Salsola tragus*).



Photo 2. View of the project area from the southeastern corner facing center.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4. View of dry hole markers for 067-08282 and 067-07243 from the southwestern portion of the project area facing center.