



Photo 1. View of the western portion of the project area from the southwestern corner facing northward.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing southward. Revegetation is sparse in this area.



Photo 5. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is sparse in this area.