

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/27/2016  
Submitted Date:  
10/31/2016  
Document Number:  
673403810

**FIELD INSPECTION FORM**

Loc ID 313235 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 6975  
Name of Operator: BEARTOOTH OIL & GAS COMPANY  
Address: P O BOX 398  
City: FRUITA State: CO Zip: 81521-

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
currey, ken	(970) 858-4158	bogcken@180com.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279201	WELL	PR	07/15/2006	GW	081-07239	VISINTAINER 11-6-8-90	PR

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	#	corrective date
Bird Protectors		
Comment:		
Corrective Action:		Date:
Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Gas Meter Run	# 1	

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		40.677910,-107.537760
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 279201 Type: WELL API Number: 081-07239 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT