

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2016

Submitted Date:

10/25/2016

Document Number:

679901970**FIELD INSPECTION FORM**

Loc ID 420617 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 420618 | WELL | PR | 03/09/2011 | GW | 125-11946 | RMR Ranch 14-36 | PR |

General Comment:

Location

| | | | |
|--------------------|---------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail along edge of farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit, wellhead, VGS and meter run | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator 50% buried by meter run | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Electric panel and telemetry equipment | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | | |
|-----------------------------|------------------------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 420618 | Type: WELL | API Number: 125-11946 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing. Casing production | | | |
| Corrective Action: | | | | Date: |

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT