

# Final Reclamation Inspection



**Photo 1.** Photo taken from approximate center of location, facing West. Final land use has changed to housing development.



# Final Reclamation Inspection



**Photo 2.** Photo taken from approximate center of location, facing North. Final land use has changed to housing development.



# Final Reclamation Inspection



**Photo 3.** Photo taken from approximate center of location, facing East. Final land use has changed to housing development.

# Final Reclamation Inspection



**Photo 4.** Photo taken from approximate center of location, facing South. Final land use has changed to housing development.