

Final Reclamation Inspection



Photo 1. Photo taken from approximate center of location, facing West. No evidence of wellbore. Active water well owned by City of Arvada.

Final Reclamation Inspection



Photo 2. Photo taken from approximate center of location, facing North. No evidence of wellbore.

Final Reclamation Inspection



Photo 3. Photo taken from approximate center of location, facing East. No evidence of wellbore.

Final Reclamation Inspection



Photo 4. Photo taken from approximate center of location, facing South. No evidence of wellbore.

Final Reclamation Inspection



Photo 5. Reference photo taken northeast of location, facing North.