

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2016

Submitted Date:

11/02/2016

Document Number:

666802700**FIELD INSPECTION FORM**

Loc ID 322467	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b>
2A Doc Num: _____			<input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b>			<b>Findings:</b>
OGCC Operator Number: <u>96850</u>			<u>5</u> Number of Comments
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>			<u>0</u> Number of Corrective Actions
Address: <u>PO BOX 370</u>			<input type="checkbox"/> Corrective Action Response Requested
City: <u>PARACHUTE</u>	State: <u>CO</u>	Zip: <u>81635</u>	

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210569	WELL	PR	10/03/1987	GW	045-06325	SUPERIOR MWX 1	PR

**General Comment:**

Two 300 bbl tanks on north side of location with no labels belong to land owner,

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

STORAGE OF SUPL

Comment:

Landowners agricultural equipmet stored on location

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Chemical unit at wellhead

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tanak ID

SE GPS

PRODUCED WATER

1

&lt;100 BBLS

STEEL AST

39.483506,-107.880665

Comment:

Corrective Action:

Date:

**Paint**

Condition

Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Inspector Name: Murray, Richard

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210569	Type:	WELL	API Number:	045-06325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:				Date:					

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT