

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

666802679**FIELD INSPECTION FORM**

Loc ID 423182	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>																																																																																																																																											
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Contact, General</td> <td></td> <td>cogcc.inspections@encana.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	Contact, General		cogcc.inspections@encana.com																																																																																																																																
Contact Name	Phone	Email	Comment																																																																																																																																								
Contact, General		cogcc.inspections@encana.com																																																																																																																																									
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>423618</td><td>WELL</td><td>PR</td><td>09/17/2012</td><td>GW</td><td>045-20779</td><td>BENZEL 35-2HM (F25NWB)</td><td>PR</td></tr> <tr><td>424130</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20841</td><td>Benzel Fee 25-8E (F25NWB)</td><td>PR</td></tr> <tr><td>424139</td><td>WELL</td><td>PR</td><td>10/12/2012</td><td>GW</td><td>045-20842</td><td>Benzel Fee 25-7E (F25NWB)</td><td>PR</td></tr> <tr><td>424191</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20843</td><td>Benzel Fee 25-1A (F25NWB)</td><td>PR</td></tr> <tr><td>424193</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20844</td><td>Benzel Fee 25-1C (F25NWB)</td><td>PR</td></tr> <tr><td>424196</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20845</td><td>Benzel Fee 25-8D (F25NWB)</td><td>PR</td></tr> <tr><td>424201</td><td>WELL</td><td>PR</td><td>05/17/2012</td><td>GW</td><td>045-20846</td><td>Benzel Fee 25-8F (F25NWB)</td><td>PR</td></tr> <tr><td>424204</td><td>WELL</td><td>PR</td><td>03/13/2012</td><td>GW</td><td>045-20847</td><td>Benzel Fee 25-1B (F25NWB)</td><td>PR</td></tr> <tr><td>424206</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20848</td><td>Benzel Fee 24-16D (F25NWB)</td><td>PR</td></tr> <tr><td>424207</td><td>WELL</td><td>PR</td><td>01/01/2014</td><td>GW</td><td>045-20849</td><td>Benzel Fee 25-7D (F25NWB)</td><td>PR</td></tr> <tr><td>424256</td><td>WELL</td><td>PR</td><td>04/08/2013</td><td>GW</td><td>045-20871</td><td>BENZEL FEDERAL 24-15B (F25NWB)</td><td>PR</td></tr> <tr><td>424260</td><td>WELL</td><td>PR</td><td>04/08/2013</td><td>GW</td><td>045-20873</td><td>Benzel Fee 25-3D (F25NWB)</td><td>PR</td></tr> <tr><td>424262</td><td>WELL</td><td>PR</td><td>04/08/2013</td><td>GW</td><td>045-20874</td><td>BENZEL FEDERAL 24-14D (F25NWB)</td><td>PR</td></tr> <tr><td>424264</td><td>WELL</td><td>PR</td><td>04/08/2013</td><td>GW</td><td>045-20876</td><td>Benzel Federal 24-10E (F25NWB)</td><td>PR</td></tr> <tr><td>424265</td><td>WELL</td><td>PR</td><td>03/13/2013</td><td>GW</td><td>045-20877</td><td>BENZEL FEDERAL 24-14DD (F25NWB)</td><td>PR</td></tr> <tr><td>424266</td><td>WELL</td><td>PR</td><td>04/08/2013</td><td>GW</td><td>045-20878</td><td>BENZEL FEE 25-3A (F25NWB)</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	423618	WELL	PR	09/17/2012	GW	045-20779	BENZEL 35-2HM (F25NWB)	PR	424130	WELL	PR	01/01/2014	GW	045-20841	Benzel Fee 25-8E (F25NWB)	PR	424139	WELL	PR	10/12/2012	GW	045-20842	Benzel Fee 25-7E (F25NWB)	PR	424191	WELL	PR	01/01/2014	GW	045-20843	Benzel Fee 25-1A (F25NWB)	PR	424193	WELL	PR	01/01/2014	GW	045-20844	Benzel Fee 25-1C (F25NWB)	PR	424196	WELL	PR	01/01/2014	GW	045-20845	Benzel Fee 25-8D (F25NWB)	PR	424201	WELL	PR	05/17/2012	GW	045-20846	Benzel Fee 25-8F (F25NWB)	PR	424204	WELL	PR	03/13/2012	GW	045-20847	Benzel Fee 25-1B (F25NWB)	PR	424206	WELL	PR	01/01/2014	GW	045-20848	Benzel Fee 24-16D (F25NWB)	PR	424207	WELL	PR	01/01/2014	GW	045-20849	Benzel Fee 25-7D (F25NWB)	PR	424256	WELL	PR	04/08/2013	GW	045-20871	BENZEL FEDERAL 24-15B (F25NWB)	PR	424260	WELL	PR	04/08/2013	GW	045-20873	Benzel Fee 25-3D (F25NWB)	PR	424262	WELL	PR	04/08/2013	GW	045-20874	BENZEL FEDERAL 24-14D (F25NWB)	PR	424264	WELL	PR	04/08/2013	GW	045-20876	Benzel Federal 24-10E (F25NWB)	PR	424265	WELL	PR	03/13/2013	GW	045-20877	BENZEL FEDERAL 24-14DD (F25NWB)	PR	424266	WELL	PR	04/08/2013	GW	045-20878	BENZEL FEE 25-3A (F25NWB)	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																				
423618	WELL	PR	09/17/2012	GW	045-20779	BENZEL 35-2HM (F25NWB)	PR																																																																																																																																				
424130	WELL	PR	01/01/2014	GW	045-20841	Benzel Fee 25-8E (F25NWB)	PR																																																																																																																																				
424139	WELL	PR	10/12/2012	GW	045-20842	Benzel Fee 25-7E (F25NWB)	PR																																																																																																																																				
424191	WELL	PR	01/01/2014	GW	045-20843	Benzel Fee 25-1A (F25NWB)	PR																																																																																																																																				
424193	WELL	PR	01/01/2014	GW	045-20844	Benzel Fee 25-1C (F25NWB)	PR																																																																																																																																				
424196	WELL	PR	01/01/2014	GW	045-20845	Benzel Fee 25-8D (F25NWB)	PR																																																																																																																																				
424201	WELL	PR	05/17/2012	GW	045-20846	Benzel Fee 25-8F (F25NWB)	PR																																																																																																																																				
424204	WELL	PR	03/13/2012	GW	045-20847	Benzel Fee 25-1B (F25NWB)	PR																																																																																																																																				
424206	WELL	PR	01/01/2014	GW	045-20848	Benzel Fee 24-16D (F25NWB)	PR																																																																																																																																				
424207	WELL	PR	01/01/2014	GW	045-20849	Benzel Fee 25-7D (F25NWB)	PR																																																																																																																																				
424256	WELL	PR	04/08/2013	GW	045-20871	BENZEL FEDERAL 24-15B (F25NWB)	PR																																																																																																																																				
424260	WELL	PR	04/08/2013	GW	045-20873	Benzel Fee 25-3D (F25NWB)	PR																																																																																																																																				
424262	WELL	PR	04/08/2013	GW	045-20874	BENZEL FEDERAL 24-14D (F25NWB)	PR																																																																																																																																				
424264	WELL	PR	04/08/2013	GW	045-20876	Benzel Federal 24-10E (F25NWB)	PR																																																																																																																																				
424265	WELL	PR	03/13/2013	GW	045-20877	BENZEL FEDERAL 24-14DD (F25NWB)	PR																																																																																																																																				
424266	WELL	PR	04/08/2013	GW	045-20878	BENZEL FEE 25-3A (F25NWB)	PR																																																																																																																																				

424267	WELL	PR	04/08/2013	GW	045-20879	Benzel Federal 24-13G (F25NWB)	PR
425773	WELL	PR	04/08/2013	GW	045-21063	BENZEL FEDERAL 24-13C (F25NWB)	PR

General Comment:

[Facilities on location ID 335104](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

17

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	423618	Type:	WELL	API Number:	045-20779	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424130	Type:	WELL	API Number:	045-20841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424139	Type:	WELL	API Number:	045-20842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424191	Type:	WELL	API Number:	045-20843	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424193	Type:	WELL	API Number:	045-20844	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424196	Type:	WELL	API Number:	045-20845	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424201	Type:	WELL	API Number:	045-20846	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424204	Type:	WELL	API Number:	045-20847	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	424206	Type:	WELL	API Number:	045-20848	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424207	Type:	WELL	API Number:	045-20849	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424256	Type:	WELL	API Number:	045-20871	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424260	Type:	WELL	API Number:	045-20873	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424262	Type:	WELL	API Number:	045-20874	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424264	Type:	WELL	API Number:	045-20876	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424265	Type:	WELL	API Number:	045-20877	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	424266	Type:	WELL	API Number:	045-20878	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	424267	Type:	WELL	API Number:	045-20879	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	425773	Type:	WELL	API Number:	045-21063	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Retention Ponds	Pass					
Ditches	Pass					
		Culverts	Pass			
		Ditches	Pass			
Waddles	Pass					
		Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802679	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986562