

HALLIBURTON

iCem[®] Service

NOBLE ENERGY INC

Date: Saturday, August 20, 2016

Lapp A15-625

Production

Job Date: Friday, August 19, 2016

Sincerely,
Lauren Roberts

Legal Notice

Warning Disclaimer

Although the information contained in this report is based on sound engineering practices, the copyright owner(s) does (do) not accept any responsibility whatsoever, in negligence or otherwise, for any loss or damage arising from the possession or use of the report whether in terms of correctness or otherwise. The application, therefore, by the user of this report or any part thereof, is solely at the user's own risk.

Limitations of Liability

Except as expressly set forth herein, there are no representations or warranties by Halliburton, express or implied, including implied warranties of merchantability and/or fitness for a particular purpose. In no event will Halliburton or its suppliers be liable for consequential, incidental, special, punitive or exemplary damages (including, without limitation, loss of data, profits, use of hardware, or software). Customer accepts full responsibility for any investment made based on results from the Software. Any interpretations, analyses or modeling of any data, including, but not limited to Customer data, and any recommendation or decisions based upon such interpretations, analyses or modeling are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and assumptions are not infallible, and with respect to which professional may differ. Accordingly, Halliburton cannot and does not warrant the accuracy, correctness or completeness of any such interpretation, recommendation, modeling or other products of the Software Product. As such, any interpretation, recommendation or modeling resulting from the Software for the purpose of any drilling, well treatment, production or financial decision will be at the sole risk of Customer. Under no circumstances will Halliburton or its suppliers be liable for any damages.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

3.0 Attachments..... 9

 3.1 Case 1-Custom Results.png.....9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Lapp A15-625** cement **Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

29 bbl. of Tuned Spacer III returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton [Ft. Lupton]

The Road to Excellence Starts with Safety

Sold To #: 345242		Ship To #: 3723530		Quote #:		Sales Order #: 0903485338					
Customer: NOBLE ENERGY INC - EBUS				Customer Rep: Cliff							
Well Name: LAPP			Well #: A15-625		API/UWI #: 05-123-42818-00						
Field: WATTENBERG		City (SAP): GILL		County/Parish: WELD		State: COLORADO					
Legal Description: SW SW-13-6N-64W-842FSL-400FWL											
Contractor: H & P DRLG				Rig/Platform Name/Num: H & P 524							
Job BOM: 7523											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA\HB61755				Srv Supervisor: Vaughn Oteri							
Job											
Formation Name											
Formation Depth (MD)		Top		Bottom							
Form Type				BHST		230 degF					
Job depth MD		17233ft		Job Depth TVD							
Water Depth				Wk Ht Above Floor							
Perforation Depth (MD)		From		To							
Well Data											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Casing		9.625	8.921	36			0	1930	0	1930	
Casing		5.5	4.778	20			0	17226	0	6695	
Open Hole Section			8.5				1930	17233	1930	6695	
Tools and Accessories											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Guide Shoe	5.5					Top Plug	5.5	1	HES		
Float Shoe	5.5			17226		Bottom Plug	5.5	2	HES		
Float Collar	5.5			17186		SSR plug set	5.5		HES		
Insert Float	5.5					Plug Container	5.5		HES		
Stage Tool	5.5					Centralizers	5.5		HES		
Fluid Data											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	11 lb/gal Tuned Spacer III	Tuned Spacer III			40	bbl	11	4.72		5	

Fluid #	Stage Type	Fluid Name		Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	11 lb/gal Tuned Spacer III	Tuned Spacer III		40	bbl	11	4.72		5	
Fluid #	Stage Type	Fluid Name		Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Elasticem w/o CBL	ELASTICEM (TM) SYSTEM		150	sack	13.2	1.57		5	7.53
7.53 Gal		FRESH WATER								
Fluid #	Stage Type	Fluid Name		Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
4	ElastiCem W/ CBL	ELASTICEM (TM) SYSTEM		620	sack	13.2	1.6		5	7.69
7.69 Gal		FRESH WATER								
Fluid #	Stage Type	Fluid Name		Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
5	EconoCem	ECONOCEM (TM) SYSTEM		1483	sack	13.5	1.68		5	7.98
Fluid #	Stage Type	Fluid Name		Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
6	Displacement	Displacement		379	bbl	8.33				
Cement Left In Pipe		Amount	42 ft			Reason			Shoe Joint	
Comment 29bbl of spacer back to surface estimated HOTC-10857.89 TOTC-6368.11 HOLC-5303.4 TOLC-1064.71 HOS-1064.71										

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	PS Pump Rate (bbl/min)	DS Pump Rate (bbl/min)	Comments
Event	1	Call Out	Call Out	8/18/2016	16:00:00	USER					Call out from Arc hub
Event	2	Arrive at Rig	Arrive at Rig	8/18/2016	20:00:00	USER					Requested on location 2200 Arrived on location met with company rep to discuss job process and concerns advised they still had a couple racks of casing left to run
Event	3	Other	Other	8/18/2016	20:03:00	USER					TD-17233 TP-17226 FC-17186 SUF-1930 MUD-9.9
Event	4	Start Job	Start Job	8/19/2016	00:33:25	COM4	-2.00	8.36	0.00	0.00	Held pre-job safety meeting with all hands on location to discuss job process and hazards
Event	5	Check Weight	Check weight	8/19/2016	00:33:26	COM4	-2.00	8.36	0.00	0.00	Confirm weight on scales 11.0ppg
Event	6	Other	Other	8/19/2016	00:34:11	COM4	1.00	0.87	0.40	0.00	Primed pumps and lines with fresh water
Event	7	Test Lines	Test Lines	8/19/2016	00:37:28	COM4	92.00	8.40	0.00	0.00	Pressure tested pumps and lines found no leaks and pressure held good 4879psi
Event	8	Drop Bottom Plug	Drop Bottom Plug	8/19/2016	00:42:28	COM4	48.00	8.38	0.00	0.00	Released plug witnessed by company rep
Event	9	Pump Spacer 1	Pump Spacer 1	8/19/2016	00:42:29	COM4	48.00	8.38	0.00	0.00	Mixed 80bbl of 11.0ppg Tuned Spacer III 40 with surfactants at 4.0bpm 430psi
Event	10	Drop Bottom Plug	Drop Bottom Plug	8/19/2016	01:03:05	COM4	91.00	10.87	0.00	2.00	Released plug witnessed by company rep
Event	11	Check Weight	Check weight	8/19/2016	01:07:27	COM4	52.00	10.68	0.00	0.00	Confirm weight of 13.2ppg on scales
Event	12	Pump Lead Cement	Pump Lead Cement	8/19/2016	01:13:04	COM4	818.00	13.12	7.00	0.00	Mixed 770sks or 219bbl of 13.2ppg y-1.57 g/sk 7.53 ElastiCem at 8.0bpm 715psi
Event	13	Other	Other	8/19/2016	01:49:07	COM4	418.00	13.17	4.50	0.80	Slowed rate due to poor bulk delivery out of trailer#11764052
Event	14	Pump Tail Cement	Pump Tail Cement	8/19/2016	01:51:27	COM4	236.00	13.46	2.00	0.80	Mixed 1483sks or 443bbl of 13.5ppg y-1.68 g/sk 7.98 EconoCem at 8.0bpm 1004psi
Event	15	Check Weight	Check weight	8/19/2016	01:54:11	COM4	1072.00	13.43	4.10	4.10	Confirm weight of 13.5ppg on scales

Event	16	Check Weight	Check weight	8/19/2016	02:19:07	COM4	1075.00	13.43	4.10	4.10	Confirm weight on scales of 13.5ppg
Event	17	Shutdown	Shutdown	8/19/2016	02:47:05	USER	27.00	13.23	0.40	0.00	
Event	18	Drop Top Plug	Drop Top Plug	8/19/2016	02:47:09	COM4	26.00	13.44	0.40	0.00	Released plug witnessed by company rep
Event	19	Clean Lines	Clean Lines	8/19/2016	02:47:23	COM4	24.00	13.96	0.40	0.00	Washed pumps and lines with fresh water
Event	20	Pump Displacement	Pump Displacement	8/19/2016	02:58:48	COM4	21.00	8.13	0.00	0.00	Pumped 379bbl of fresh water to displace cement
Event	21	Bump Plug	Bump Plug	8/19/2016	03:40:23	COM4	2444.00	8.41	0.00	0.00	Bumped plug 500psi over final pump pressure 1882/2576 psi
Event	22	Other	Other	8/19/2016	03:46:09	COM4					Released pressure back to pump truck to check floats, floats held good 4.5bbl back to truck
Event	23	End Job	End Job	8/19/2016	03:49:03	COM4	17.00	8.35	0.00	0.00	29bbl of spacer back to surface estimated HOTC-10857.89 TOTC-6368.11 HOLC-5303.4 TOLC-1064.71 HOS-1064.71

3.0 Attachments

3.1 Case 1-Custom Results.png

