

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2016

Submitted Date:

10/31/2016

Document Number:

675203531**FIELD INSPECTION FORM**

Loc ID 335008	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	------------------------------------	---	-------------------

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210976	WELL	PR	11/16/2009	GW	045-06734	GRAND VALLEY RANCH CO GV 84-1	PR
291572	WELL	PR	07/02/2008	GW	045-14466	DIAMOND ELK PA 522-1	PR
291574	WELL	PR	07/26/2007	GW	045-14465	DIAMOND ELK PA 324-1	PR
291575	WELL	PR	07/26/2007	GW	045-14464	DIAMOND ELK PA 23-1	PR
291576	WELL	PR	04/21/2008	GW	045-14463	DIAMOND ELK PA 423-1	PR
291577	WELL	PR	04/21/2008	GW	045-14462	DIAMOND ELK PA 424-1	PR
291578	WELL	PR	04/21/2008	GW	045-14461	DIAMOND ELK PA512-1	PR
291579	WELL	PR	04/21/2008	GW	045-14460	DIAMOND ELK PA 313-1	PR
291580	WELL	PR	11/28/2008	GW	045-14459	DIAMOND ELK PA 413-1	PR
291581	WELL	PR	04/21/2008	GW	045-14458	DIAMOND ELK PA 513-1	PR
291582	WELL	PR	11/28/2008	GW	045-14457	DIAMOND ELK PA 314-1	PR
291583	WELL	PR	11/28/2008	GW	045-14456	DIAMOND ELK PA 14-1	PR
291584	WELL	PR	04/21/2008	GW	045-14455	DIAMOND ELK PA 524-1	PR
291585	WELL	PR	07/26/2007	GW	045-14454	DIAMOND ELK PA 523-1	PR
291586	WELL	PR	04/21/2008	GW	045-14453	DIAMOND ELK PA 24-1	PR
291590	WELL	PR	04/21/2008	GW	045-14449	DIAMOND ELK PA 323-1	PR
291591	WELL	PR	11/28/2008	GW	045-14448	DIAMOND ELK PA 414-1	PR
424275	WELL	PR	06/10/2013	GW	045-20881	Diamond Elk, LLC PA 334-2	PR
424276	WELL	PR	04/15/2013	GW	045-20882	Diamond Elk, LLC PA 434-2	PR
424277	WELL	PR	04/15/2013	GW	045-20883	Diamond Elk, LLC PA 534-2	PR
424278	WELL	PR	08/08/2013	GW	045-20884	Diamond Elk, LLC PA 33-2	PR
424279	WELL	PR	07/05/2013	GW	045-20885	Diamond Elk, LLC PA 333-2	PR
424285	WELL	PR	06/10/2013	GW	045-20886	Diamond Elk, LLC PA 34-2	PR

424287	WELL	PR	06/10/2013	GW	045-20887	Diamond Elk, LLC PA 433-2	PR
424354	WELL	PR	06/10/2013	GW	045-20888	Diamond Elk, LLC PA 543-2	PR
424355	WELL	PR	06/10/2013	GW	045-20889	Diamond Elk, LLC PA 443-2	PR
424358	WELL	PR	08/08/2013	GW	045-20892	Diamond Elk, LLC PA 343-2	PR
424361	WELL	PR	04/15/2013	GW	045-20895	Diamond Elk, LLC PA 344-2	PR
424364	WELL	PR	05/31/2013	GW	045-20898	Diamond Elk, LLC PA 44-2	PR
424366	WELL	PR	03/26/2013	GW	045-20900	Diamond Elk, LLC PA 444-2	PR
424367	WELL	PR	07/02/2013	GW	045-20901	Diamond Elk, LLC PA 43-2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date: <input type="text"/>	

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	<input type="text"/>				

Inspected Facilities				
Facility ID: <u>210976</u>	Type: <u>WELL</u>	API Number: <u>045-06734</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291572</u>	Type: <u>WELL</u>	API Number: <u>045-14466</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291574</u>	Type: <u>WELL</u>	API Number: <u>045-14465</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291575</u>	Type: <u>WELL</u>	API Number: <u>045-14464</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291576</u>	Type: <u>WELL</u>	API Number: <u>045-14463</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291577</u>	Type: <u>WELL</u>	API Number: <u>045-14462</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291578</u>	Type: <u>WELL</u>	API Number: <u>045-14461</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291579</u>	Type: <u>WELL</u>	API Number: <u>045-14460</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291580</u>	Type: <u>WELL</u>	API Number: <u>045-14459</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291581</u>	Type: <u>WELL</u>	API Number: <u>045-14458</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291582</u>	Type: <u>WELL</u>	API Number: <u>045-14457</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291583</u>	Type: <u>WELL</u>	API Number: <u>045-14456</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291584</u>	Type: <u>WELL</u>	API Number: <u>045-14455</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291585</u>	Type: <u>WELL</u>	API Number: <u>045-14454</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291586</u>	Type: <u>WELL</u>	API Number: <u>045-14453</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291590</u>	Type: <u>WELL</u>	API Number: <u>045-14449</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291591</u>	Type: <u>WELL</u>	API Number: <u>045-14448</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>424275</u>	Type: <u>WELL</u>	API Number: <u>045-20881</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>424276</u>	Type: <u>WELL</u>	API Number: <u>045-20882</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Facility ID:	<u>424277</u>	Type:	<u>WELL</u>	API Number:	<u>045-20883</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424278</u>	Type:	<u>WELL</u>	API Number:	<u>045-20884</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424279</u>	Type:	<u>WELL</u>	API Number:	<u>045-20885</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424285</u>	Type:	<u>WELL</u>	API Number:	<u>045-20886</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424287</u>	Type:	<u>WELL</u>	API Number:	<u>045-20887</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424354</u>	Type:	<u>WELL</u>	API Number:	<u>045-20888</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424355</u>	Type:	<u>WELL</u>	API Number:	<u>045-20889</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424358</u>	Type:	<u>WELL</u>	API Number:	<u>045-20892</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424361</u>	Type:	<u>WELL</u>	API Number:	<u>045-20895</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424364</u>	Type:	<u>WELL</u>	API Number:	<u>045-20898</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424366</u>	Type:	<u>WELL</u>	API Number:	<u>045-20900</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>424367</u>	Type:	<u>WELL</u>	API Number:	<u>045-20901</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					
Check Dams	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203531	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3988990