

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2016

Submitted Date:

11/04/2016

Document Number:

674703308**FIELD INSPECTION FORM**
 Loc ID 335113 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275241	WELL	PR	10/09/2006	GW	045-13497	CASCADE CREEK 632-13-22	PR
282426	WELL	PR	06/06/2007	GW	045-11766	CASCADE CREEK 697-32-12D	PR
282427	WELL	PR	05/17/2007	GW	045-11767	CASCADE CREEK 697-29-59D	PR
282428	WELL	PR	05/17/2007	GW	045-11768	CASCADE CREEK 697-29-60D	PR
282429	WELL	PR	03/02/2016	GW	045-11769	CASCADE CREEK 697-32-09D	PR
282430	WELL	PR	06/01/2008	GW	045-11770	CASCADE CREEK 697-32-18D	PR
288549	WELL	PR	05/19/2010	GW	045-13290	CASCADE CREEK 697-32-10D	PR
288553	WELL	PR	05/17/2007	GW	045-13291	CASCADE CREEK 697-32-01D	PR
288554	WELL	PR	05/17/2007	GW	045-13292	CASCADE CREEK 697-32-03D	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container at wells		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
----------	---	----------	------	----------	--------	--

METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gallons	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities									
Facility ID:	275241	Type:	WELL	API Number:	045-13497	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282426	Type:	WELL	API Number:	045-11766	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282427	Type:	WELL	API Number:	045-11767	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282428	Type:	WELL	API Number:	045-11768	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282429	Type:	WELL	API Number:	045-11769	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282430	Type:	WELL	API Number:	045-11770	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	288549	Type:	WELL	API Number:	045-13290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	288553	Type:	WELL	API Number:	045-13291	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Compaction	Pass			
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
Compaction	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT