

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2016

Submitted Date:

11/09/2016

Document Number:

672500153**FIELD INSPECTION FORM**

Loc ID 329282 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 249301      | WELL | PR     | 03/05/2010  | OW         | 123-17103 | RUMSEY 35-15  | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | SEPARATOR    |       |  |
| Comment:           | WIRE         |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | AG PANEL     |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | WIRE         |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors             | # 2 |       | corrective date |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |

|   |     |       |
|---|-----|-------|
| Comment: <b>ANCHORED</b>                    |     | Date: |
| Corrective Action:                          |     | Date: |
| Type: Gas Meter Run                         | # 1 |       |
| Comment:                                    |     |       |
| Corrective Action:                          |     | Date: |
| Type: Ancillary equipment                   | # 1 |       |
| Comment: <b>METHONAL PUMP W/CONTAINMENT</b> |     |       |
| Corrective Action:                          |     | Date: |
| Type: Emission Control Device               | # 1 |       |
| Comment:                                    |     |       |
| Corrective Action:                          |     | Date: |

**Tanks and Berms:**

| Contents                 | # | Capacity | Type                | Tanak ID | SE GPS                |
|--------------------------|---|----------|---------------------|----------|-----------------------|
| PRODUCED WATER           | 1 | <50 BBLs | CONCRETE SUMP/VAULT |          | 40.350390,-104.742000 |
| Comment: <b>ANCHORED</b> |   |          |                     |          |                       |
| Corrective Action:       |   |          |                     |          | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents                 | # | Capacity | Type      | Tanak ID | SE GPS                |
|--------------------------|---|----------|-----------|----------|-----------------------|
| CRUDE OIL                | 1 | 300 BBLs | STEEL AST |          | 40.350390,-104.742000 |
| Comment: <b>ANCHORED</b> |   |          |           |          |                       |
| Corrective Action:       |   |          |           |          | Date:                 |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |



**Inspected Facilities**Facility ID: 249301 Type: WELL API Number: 123-17103 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **BradenHead**Comment: PLUMBED TO SURFACECorrective Action: Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? PassSegregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**CroplandTop soil replaced PassRecontoured Pass

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐Multi-Well Location ☐

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT