

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203548**FIELD INSPECTION FORM**

Loc ID 336047	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>6301 DEAUVILLE BLVD</u> City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>				<b>Findings:</b> 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276275	WELL	PR	12/15/2005	GW	045-10434	SKINNER RIDGE 598-25-3	PR
293971	WELL	PR	11/22/2009	GW	045-15182	SKR 598-25-AV-01	PR
293972	WELL	PR	11/20/2009	GW	045-15183	SKR 598-25-AV-03	PR
293973	WELL	PR	11/14/2009	GW	045-15184	SKR 598-25-AV-05	PR
293974	WELL	PR	08/30/2013	GW	045-15185	SKR 598-25-AV-06	PR
293975	WELL	PR	10/11/2009	GW	045-15186	SKR 598-25-AV-02	PR
293976	WELL	PR	08/30/2013	GW	045-15187	SKR 598-25-AV-11	PR
293977	WELL	PR	10/08/2009	GW	045-15188	SKR 598-25-AV-04	PR
293978	WELL	PR	08/30/2013	GW	045-15189	SKR 598-25-AV-08	PR
293979	WELL	PR	12/08/2009	GW	045-15190	SKR 598-25-AV-14	PR
293980	WELL	PR	11/17/2009	GW	045-15191	SKR 598-25-AV-07	PR
293981	WELL	PR	02/01/2011	GW	045-15192	SKR 598-25-AV-15	PR
293982	WELL	PR	08/15/2012	GW	045-15193	SKR 598-25-AV-13	PR
293985	WELL	PR	11/07/2009	GW	045-15195	SKR 598-25-AV-09	PR
293990	WELL	PR	09/30/2009	GW	045-15196	SKR 598-25-AV-10	PR
293993	WELL	PR	12/08/2009	GW	045-15197	SKR 598-25-AV-12	PR
294087	WELL	PR	08/01/2013	GW	045-15243	SKR 598-25-AV-20	PR
294110	WELL	PR	08/07/2015	GW	045-15254	SKR 598-25-AV 19	PR
294112	WELL	PR	02/01/2011	GW	045-15255	SKR 598-25-AV-21	PR
294113	WELL	PR	08/30/2013	GW	045-15256	SKR 598-25-AV-16	PR
294114	WELL	PR	08/30/2013	GW	045-15257	SKR 598-25-AV-22	PR
294116	WELL	PR	02/09/2010	GW	045-15258	SKR 598-25-AV-18	PR
294117	WELL	PR	10/25/2009	GW	045-15259	SKR 598-25-AV-17	PR

**General Comment:**

--

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>276275</u>	Type: <u>WELL</u>	API Number: <u>045-10434</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293971</u>	Type: <u>WELL</u>	API Number: <u>045-15182</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293972</u>	Type: <u>WELL</u>	API Number: <u>045-15183</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293973</u>	Type: <u>WELL</u>	API Number: <u>045-15184</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293974</u>	Type: <u>WELL</u>	API Number: <u>045-15185</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293975</u>	Type: <u>WELL</u>	API Number: <u>045-15186</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293976</u>	Type: <u>WELL</u>	API Number: <u>045-15187</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293977</u>	Type: <u>WELL</u>	API Number: <u>045-15188</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293978</u>	Type: <u>WELL</u>	API Number: <u>045-15189</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293979</u>	Type: <u>WELL</u>	API Number: <u>045-15190</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293980</u>	Type: <u>WELL</u>	API Number: <u>045-15191</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293981</u>	Type: <u>WELL</u>	API Number: <u>045-15192</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293982</u>	Type: <u>WELL</u>	API Number: <u>045-15193</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293985</u>	Type: <u>WELL</u>	API Number: <u>045-15195</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293990</u>	Type: <u>WELL</u>	API Number: <u>045-15196</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>293993</u>	Type: <u>WELL</u>	API Number: <u>045-15197</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294087</u>	Type: <u>WELL</u>	API Number: <u>045-15243</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294110</u>	Type: <u>WELL</u>	API Number: <u>045-15254</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>294112</u>	Type: <u>WELL</u>	API Number: <u>045-15255</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Inspector Name: CONKLIN, CURTIS

Facility ID:	294113	Type:	WELL	API Number:	045-15256	Status:	PR	Insp. Status:	PR
Facility ID:	294114	Type:	WELL	API Number:	045-15257	Status:	PR	Insp. Status:	PR
Facility ID:	294116	Type:	WELL	API Number:	045-15258	Status:	PR	Insp. Status:	PR
Facility ID:	294117	Type:	WELL	API Number:	045-15259	Status:	PR	Insp. Status:	PR

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Check Dams	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203548	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993665">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993665</a>