



Photo#1: Overview of Location from Entry to South.

November 3, 2016

Inspection Photos: Laramie Griffith Loc#334445



Photo#2: Piles of Materials/Debris at South end of Location in Interim Reclamation area.

November 3, 2016

Inspection Photos: Laramie Griffith Loc#334445

Photo#3:

Open Cellar at SW end of Pad needs to be covered.

Photo#4

