

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/07/2016  
Submitted Date:  
11/07/2016  
Document Number:  
675203562

**FIELD INSPECTION FORM**

Loc ID 442832 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 1050 17TH STREET #1700  
City: DENVER State: CO Zip: 80265

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>
Ellsworth, Stuart		Stuart.ellsworth@state.co.us	<a href="#">Engineering Supervisor</a>
Bleil, Rob	(970) 329-4373	rbleil@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442837	WELL	DG	10/17/2016	LO	045-22917	MONUMENT RIDGE B 44D-08-07-95	DG

**General Comment:**

[Drilling Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 442837 Type: WELL API Number: 045-22917 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: CapStart 321 Pusher/Rig Manager: Richard McNeil  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: Naturita, CO

**Comment:** BOP tested on 11/6

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203562	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4001045">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4001045</a>