

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2016

Submitted Date:

11/14/2016

Document Number:

681901700**FIELD INSPECTION FORM**
 Loc ID 446290 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446284	WELL	XX	06/22/2016		123-43298	Morgan Hills 1A-7H-A168	XX
446286	WELL	XX	06/22/2016		123-43300	Morgan Hills 1C-7H-A168	XX
446287	WELL	XX	06/22/2016		123-43301	Morgan Hills 1B-7H-A168	XX

General Comment:

Inspected Facilities

Facility ID: 446284 Type: WELL API Number: 123-43298 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: Ensign - 122 Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446286 Type: WELL API Number: 123-43300 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: Ensign -122 Pusher/Rig Manager: Robert Samples
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: _____

Comment: Ensign Rig 122 drilling surface casing.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446287 Type: WELL API Number: 123-43301 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

**Drill Fluids
Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment: [Surface casing set and cemented.](#)

Corrective Action: _____

Date: _____

BradenHead

Comment: [No Bradenhead.](#)

Corrective Action: _____

Date: _____