

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2016

Submitted Date:

11/17/2016

Document Number:

685501367**FIELD INSPECTION FORM**Loc ID 431392 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harter, Laura		lharter@gwogco.com	<a href="#">regulatory</a>
,		inspections@gwogco.com	<a href="#">All Inspections</a>
Musgrave, Tim	970-768-6097	tmusgrave@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431393	WELL	PR	12/04/2013	OW	123-36585	Land JG 31-13D	PR
431394	WELL	PR	05/01/2015	OW	123-36586	Land JG 31-36D	PR
431396	WELL	XX	01/17/2013	LO	123-36588	Land JG 31-34D	ND
431397	WELL	DG	02/08/2013	SI	123-36589	Land JG 31-35D	WO
431398	WELL	XX	03/21/2013	LO	123-36590	Land JG 31-25D	ND
431400	WELL	DG	03/17/2013	SI	123-36591	Land JG 31-18D	DG
431401	WELL	PR	12/04/2013	GW	123-36592	Land JG 31-19D	PR
431402	WELL	PR	12/04/2013	OW	123-36593	Land JG 31-17D	PR
431403	WELL	PR	12/04/2013	OW	123-36594	Land JG 31-24D	PR
431404	WELL	DG	02/17/2013	SI	123-36595	Land JG 31-20D	WO
431444	WELL	DG	03/04/2013	SI	123-36608	Land JG 31-12D	WO
431445	WELL	XX	01/25/2013	LO	123-36609	Land JG 31-33D	ND
431447	WELL	DG	03/21/2013	SI	123-36610	Land JG 31-32D	WO

**General Comment:**

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	OK		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	ROD IRON FENCING AROUND ALL WELLHEADS SE CORNER N40.08804 W-104.59927		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 5		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:	NO AIRS NUMBER		
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	431393	Type:	WELL	API Number: 123-36585	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
<b>BradenHead</b>						
Comment:	BRADERNHEAD PLUMBED TO SURFACE					
Corrective Action:						Date:
Facility ID:	431394	Type:	WELL	API Number: 123-36586	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
<b>BradenHead</b>						
Comment:	BRADENHEAD PLUMBED TO SURFACE					
Corrective Action:						Date:
Facility ID:	431396	Type:	WELL	API Number: 123-36588	Status: XX	Insp. Status: ND
Facility ID:	431397	Type:	WELL	API Number: 123-36589	Status: DG	Insp. Status: WO
Facility ID:	431398	Type:	WELL	API Number: 123-36590	Status: XX	Insp. Status: ND
Facility ID:	431400	Type:	WELL	API Number: 123-36591	Status: DG	Insp. Status: DG
Facility ID:	431401	Type:	WELL	API Number: 123-36592	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:
<b>BradenHead</b>						
Comment:	BRADENHEAD PLUMBED TO SURFACE					
Corrective Action:						Date:
Facility ID:	431402	Type:	WELL	API Number: 123-36593	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	PR					
Corrective Action:						Date:

**BradenHead**Comment: BRADENHEAD PLUMBED TO SURFACECorrective Action: Date: Facility ID: 431403 Type: WELL API Number: 123-36594 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: **BradenHead**Comment: BRADENHEAD PLUMBED TO SURFACECorrective Action: Date: Facility ID: 431404 Type: WELL API Number: 123-36595 Status: DG Insp. Status: WOFacility ID: 431444 Type: WELL API Number: 123-36608 Status: DG Insp. Status: WOFacility ID: 431445 Type: WELL API Number: 123-36609 Status: XX Insp. Status: NDFacility ID: 431447 Type: WELL API Number: 123-36610 Status: DG Insp. Status: WO**COGCC Comments**

Comment

User

Date

INTERMITTER CONTROLLERS ON 5 WELLHEADS

montoyaj

11/17/2016