

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	PANEL		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
Comment:	Refer to inspection # 681901730 for information concerning shared battery and equipment.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
Comment:	Refer to inspection # 681901730 for information concerning shared battery and equipment.				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: _____					
Corrective Action: _____					Date: _____

Venting:

Yes/No	NO		
Comment: _____			
Corrective Action: _____			Date: _____

Flaring:

Type			
Comment: _____			
Corrective Action: _____			Date: _____

Location Construction

Location ID: 301377 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 159255 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 800

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: _____
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: _____
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 1200 Csg psi: 1500 BH psi: 0

Insp. Status: Pass

Comment: Pressured casing to 1500 psi. Held for 15 min. with no decrease.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT