

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2016

Submitted Date:

11/17/2016

Document Number:

685501367**FIELD INSPECTION FORM**

Loc ID 431392	Inspector Name: MONTOYA, JOHN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10110</u> Name of Operator: <u>GREAT WESTERN OPERATING COMPANY LLC</u> Address: <u>1801 BROADWAY #500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>17</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Harter, Laura		lharter@gwogco.com	regulatory
,		inspections@gwogco.com	All Inspections
Musgrave, Tim	970-768-6097	tmusgrave@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431393	WELL	PR	12/04/2013	OW	123-36585	Land JG 31-13D	PR
431394	WELL	PR	05/01/2015	OW	123-36586	Land JG 31-36D	PR
431396	WELL	XX	01/17/2013	LO	123-36588	Land JG 31-34D	ND
431397	WELL	DG	02/08/2013	SI	123-36589	Land JG 31-35D	WO
431398	WELL	XX	03/21/2013	LO	123-36590	Land JG 31-25D	ND
431400	WELL	DG	03/17/2013	SI	123-36591	Land JG 31-18D	DG
431401	WELL	PR	12/04/2013	GW	123-36592	Land JG 31-19D	PR
431402	WELL	PR	12/04/2013	OW	123-36593	Land JG 31-17D	PR
431403	WELL	PR	12/04/2013	OW	123-36594	Land JG 31-24D	PR
431404	WELL	DG	02/17/2013	SI	123-36595	Land JG 31-20D	WO
431444	WELL	DG	03/04/2013	SI	123-36608	Land JG 31-12D	WO
431445	WELL	XX	01/25/2013	LO	123-36609	Land JG 31-33D	ND
431447	WELL	DG	03/21/2013	SI	123-36610	Land JG 31-32D	WO

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [OK](#)

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	ROD IRON FENCING AROUND ALL WELLHEADS SE CORNER N40.08804 W-104.59927		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:	NO AIRS NUMBER		
Corrective Action:		Date:	

Flaring:			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	431393	Type:	WELL	API Number:	123-36585	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	BRADERNHEAD PLUMBED TO SURFACE								
Corrective Action:						Date:			
Facility ID:	431394	Type:	WELL	API Number:	123-36586	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	BRADENHEAD PLUMBED TO SURFACE								
Corrective Action:						Date:			
Facility ID:	431396	Type:	WELL	API Number:	123-36588	Status:	XX	Insp. Status:	ND
Facility ID:	431397	Type:	WELL	API Number:	123-36589	Status:	DG	Insp. Status:	WO
Facility ID:	431398	Type:	WELL	API Number:	123-36590	Status:	XX	Insp. Status:	ND
Facility ID:	431400	Type:	WELL	API Number:	123-36591	Status:	DG	Insp. Status:	DG
Facility ID:	431401	Type:	WELL	API Number:	123-36592	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
BradenHead									
Comment:	BRADENHEAD PLUMBED TO SURFACE								
Corrective Action:						Date:			
Facility ID:	431402	Type:	WELL	API Number:	123-36593	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

BradenHeadComment: BRADENHEAD PLUMBED TO SURFACECorrective Action: Date: Facility ID: 431403 Type: WELL API Number: 123-36594 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: **BradenHead**Comment: BRADENHEAD PLUMBED TO SURFACECorrective Action: Date: Facility ID: 431404 Type: WELL API Number: 123-36595 Status: DG Insp. Status: WOFacility ID: 431444 Type: WELL API Number: 123-36608 Status: DG Insp. Status: WOFacility ID: 431445 Type: WELL API Number: 123-36609 Status: XX Insp. Status: NDFacility ID: 431447 Type: WELL API Number: 123-36610 Status: DG Insp. Status: WO**COGCC Comments**

Comment

User

Date

INTERMITTER CONTROLLERS ON 5 WELLHEADS

montoyaj

11/17/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501367	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006300