



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Jacob Lobato (jacob.lobato@bp.com)
Submission Date:	Nov 21, 2016 5:34:11 PM MST
Server Receive Date:	Nov 21, 2016 5:34:21 PM MST
Reference Number:	20161122-1851346097
Location:	1008 E 36th St, Farmington, NM 87401, USA Nov 21, 2016 5:27:53 PM MST [ <a href="#">View Map</a> ]

## Information

Name	jacob.lobato@bp.com
Date	Nov 21, 2016
Select Run	Area 6 West
Well Name	JACQUEZ, THOMAS GAS UNIT E 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions
Picture North to South	



Picture South to North



Picture East to West



Completed work description

Removed wood wire spool, marked rig anchor, replaced location sign, and installed road construction barrel correctly with dirt around bottom for stability.