



Photo#1: View of Location from Entry Road to North; Vegetation is establishing in Interim Reclamation areas



Photo#2: Three Conductors Set on Location.

November 15, 2016

Inspection Photos: Linn Energy, GranLee, Old Mountain Loc#335617



Photo#3: Land Farming off NE corner of Pad.

Photos# 4&5:

Gate Open at North and Fence Cut at NE corners of Location.

