

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2016

Submitted Date:

11/23/2016

Document Number:

673403878**FIELD INSPECTION FORM**

Loc ID 312839 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222555	WELL	PR	07/31/1975	GW	081-05573	HIAWATHA UNIT 1	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-341-3129

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heater Treater	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate			Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 222555	Type: WELL	API Number: 081-05573	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT