



Photo#1: Overview of Location from Entry to SE

November 15, 2016

Inspection Photos: TEP AP ALs Loc#335973



Photo#2: Areas of Vegetation are struggling to Establish.

November 15, 2016

Inspection Photos: TEP AP ALs Loc#335973





Photo#3: View of Access RD from Location to West; point of origin from Main RD.





Photo#4: Reference area Vegetation to Nw of Location.

November 15, 2016

Inspection Photos: TEP AP ALs Loc#335973