

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2016

Submitted Date:

11/28/2016

Document Number:

666802742

### FIELD INSPECTION FORM

Loc ID 334763 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

- 7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287362	WELL	PR	07/02/2012	GW	045-12984	LAST DANCE 13B-2-792	PR
287577	WELL	PR	03/02/2007	GW	045-12999	LAST DANCE 13D-2-792	PR

**General Comment:**



Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	6	OTHER	STEEL AST		39.474338,-107.638970
Comment:					
Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	250bbbs				
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	YES				
Comment:	Bradenhead valves open				
Corrective Action:			Date:		
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:			Date:		

**Inspected Facilities**

Facility ID: 287362 Type: WELL API Number: 045-12984 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger Lift](#)

Corrective Action:

Date:

Facility ID: 287577 Type: WELL API Number: 045-12999 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger Lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Check Dams	Pass			
Seeding	Pass					
Gravel	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT