

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/28/2016
Submitted Date:
11/28/2016
Document Number:
681901770

FIELD INSPECTION FORM

Loc ID 446290 Inspector Name: HELGELAND, GARY On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 370 17TH STREET #2170
City: DENVER State: CO Zip: 80202

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446281	WELL	DG	11/07/2016		123-43295	Morgan Hills 1I-7H-A168	DG
446282	WELL	DG	11/12/2016		123-43296	Morgan Hills 1E-7H-A168	DG
446283	WELL	DG	11/09/2016		123-43297	Morgan Hills 1H-7H-A168	DG
446284	WELL	DG	11/15/2016		123-43298	Morgan Hills 1A-7H-A168	DG
446285	WELL	DG	11/13/2016		123-43299	Morgan Hills 1D-7H-A168	DG
446286	WELL	DG	11/14/2016		123-43300	Morgan Hills 1C-7H-A168	DG
446287	WELL	DG	11/14/2016		123-43301	Morgan Hills 1B-7H-A168	DG
446288	WELL	DG	11/11/2016		123-43302	Morgan Hills 1G-7H-A168	DG
446289	WELL	DG	11/11/2016		123-43303	Morgan Hills 1F-7H-A168	DG

General Comment:

Inspected Facilities

Facility ID: 446281 Type: WELL API Number: 123-43295 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Ensign Rig 153 Pusher/Rig Manager: Robert Samples
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: YES
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Ensign Rig #153 on location. Derrick screened for fugitive light mitigation. Sound mitigation in place. Chemicals properly stored. BOPs tested. Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446282 Type: WELL API Number: 123-43296 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446283 Type: WELL API Number: 123-43297 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446284 Type: WELL API Number: 123-43298 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____ Date: _____

Facility ID: 446285 Type: WELL API Number: 123-43299 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____ Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____

Date: _____

Facility ID: 446286 Type: WELL API Number: 123-43300 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____

Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____

Date: _____

Facility ID: 446287 Type: WELL API Number: 123-43301 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: Surface casing set and cemented.

Corrective Action: _____

Date: _____

BradenHead

Comment: No Bradenhead.

Corrective Action: _____

Date: _____

Facility ID: 446288 Type: WELL API Number: 123-43302 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Facility ID: 446289 Type: WELL API Number: 123-43303 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____