

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2016

Submitted Date:

11/22/2016

Document Number:

672500205**FIELD INSPECTION FORM**
 Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	APPROX 40' SOUND WALLS		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: ENSIGN 140 Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: WASTE MANAGEMENT
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG

Facility ID: 434335 Type: WELL API Number: 123-38106 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Pass	
				Material Handling And Spill Prevention	Pass	
Gravel	Pass			Covering Materials	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
NO VIOLATIONS OF COGCC RULES WERE OBSERVED AT THE TIME OF THIS INSPECTION	gomezj	11/22/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500205	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009469