

Cover Data

Date: 11/15/2016

Inspected By: C. Roy

Location/Operator: Kinder Morgan 083-06695

Location/Operator							
Transect #/disturbed/Ref	1 - disturbed				2 - Reference		
Transect Orientation and first photo, degrees	272 degrees westward 37.46141, -108.80407				93 degrees eastward 37.46157, -108.80439		
Photo Midpoint (2)	37.46128, -108.80432				37.46173, -108.80432		
End transect	37.46133, -108.80447				37.46158, -108.80406		
Photo other	—				—		
Aspect/Slope	~ 1 percent north west				~ 1 percent north west		
	Totals			Totals	Totals		Totals
Cryptogams (eg. Moss, lichen)							
Litter	:			2			
Bare Soil				96		28	
Rock	—			0		19	
Total Weeds	—			0			
Total Desirable Species	2				53		
80% Check	2/53 = 4 percent (No)						
	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit
<i>Agropyron cristatum</i>	:	2	—	—	:::	5	
<i>Pascopyron smithii</i>	—	—	2	—		27	
<i>Medicago sativa</i>	—	—	—	—		17	
<i>Sanguisorba minor</i>	—	—	—	—	:	2	
<i>Chrysanthamnus nauseosus</i>	—	—	—	—	.	5	
<i>Artemisia tridentata</i>	—	—	—	—	.	1	
						53	

~~2nd= second hit; P= plant species present but not hit~~