



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Interim reclamation areas are revegetating with desirable species such as smooth brome (*Bromus inermis*) and undesirable species such as yellow tumbled mustard (*Sysimbrium altissimum*).



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 4. View of the southern portion of the project area from the southwestern corner facing eastward.





Photo 5. View of erosional channel forming in the northwestern corner of the project area.