

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/21/2016

Submitted Date:

11/29/2016

Document Number:

666802751**FIELD INSPECTION FORM**

Loc ID 323932 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211290	WELL	PR	05/25/1996	GW	045-07049	LEGG 2-26-6-92	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

Landowner has stored equipment and debris on location

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

CONDENSATE

1

<100 BBLS

PBV STEEL

Comment:

Centralized battery

Corrective Action:

Date:

Paint

Condition

Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type

Capacity

Permeability (Wall)

Permeability (Base)

Maintenance

Comment:

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		39.503807,-107.633039	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valve open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 211290	Type: WELL	API Number: 045-07049	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT