

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2016

Submitted Date:

12/01/2016

Document Number:

685301889**FIELD INSPECTION FORM**
 Loc ID 326426 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON State: TX Zip: 77252-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|-----------------------------------|---------------------------------------|
| Walker, Crystal | 505-326-9837 | Crystal.Walker@cop.com | SW Inspection Reports |
| Busse, Dollie | 505-324-6104 | dollie.l.busse@conocophillips.com | SW Inspection Reports |
| Notor, Lori | 505-326-9822 | Lori.R.Notor@conocophillips.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 216475 | WELL | PR | 02/01/2011 | GW | 067-08081 | WILSON 34-9 29-1 | PR |

General Comment:

The separators/ meter run equipment for both the Wilson #29-1 and Wilson #29-4 are located in the same fenced area adjacent to Hwy 550 south. The Wilson 29-1 wellhead is located in a below grade cellar in the agricultural area NE of surface equipment. Landowner incident see inspector comments for additional information.

Location

| | | | |
|--------------------|--------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Needs maintenance. | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | 6' Chain Link Fence | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric Service | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------|
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Electric Motor with Water Transfer Equipment | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry Equipment | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 216475 | Type: WELL | API Number: 067-08081 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|---------|------------|
| Inspector was detained by landowner. There are three facilities locations on this landowners property with each well located in a below grade cellar and production facilities are located jointly on the south side of property. DO NOT ENTER through subdivision access roads. Access to wells and production facilities for the Wilson 29-1 and 29-4 are from the first left turn past CR 302. | stjohnw | 12/01/2016 |