


Photo#1:

View North over Location Center



Photo#2:

View South over Location Center




November 3, 2016

Inspection Photos: Gunderson Federal PA; API#077-08678.


Photo#3:

View East over Location Center



Photo#4:

View West over Location Center



November 3, 2016

Inspection Photos: Gunderson Federal PA; API#077-08678.

Photo#5:

Entry into Pasture & Location. Access Road to & through Pasture was in use before Drilling of Well. Land Owner Sheep Camp is parked on Location.



November 3, 2016

Inspection Photos: Gunderson Federal PA; API#077-08678.