

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2016

Submitted Date:

11/28/2016

Document Number:

666802746**FIELD INSPECTION FORM**

Loc ID 334666	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Contact, General</td> <td></td> <td>cogcc.inspections@encana.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	Contact, General		cogcc.inspections@encana.com																																																																																
Contact Name	Phone	Email	Comment																																																																																								
Contact, General		cogcc.inspections@encana.com																																																																																									
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>285781</td><td>WELL</td><td>PR</td><td>01/06/2007</td><td>GW</td><td>045-12515</td><td>JUNIPER 1-13A (M1E)</td><td>PR</td></tr> <tr><td>285875</td><td>WELL</td><td>PR</td><td>12/27/2006</td><td>GW</td><td>045-12582</td><td>JUNIPER 2-16A (M1E)</td><td>PR</td></tr> <tr><td>285876</td><td>WELL</td><td>PR</td><td>12/30/2006</td><td>GW</td><td>045-12581</td><td>JUNIPER 2-16 (M1E)</td><td>PR</td></tr> <tr><td>285877</td><td>WELL</td><td>PR</td><td>12/19/2006</td><td>GW</td><td>045-12580</td><td>JUNIPER 1-13 (M1E)</td><td>PR</td></tr> <tr><td>296480</td><td>WELL</td><td>PR</td><td>10/23/2008</td><td>GW</td><td>045-16049</td><td>JUNIPER 1-12A (M1E)</td><td>PR</td></tr> <tr><td>296481</td><td>WELL</td><td>PR</td><td>10/09/2008</td><td>GW</td><td>045-16050</td><td>JUNIPER 2-9(M1E)</td><td>PR</td></tr> <tr><td>296482</td><td>WELL</td><td>PR</td><td>10/19/2008</td><td>GW</td><td>045-16051</td><td>JUNIPER 1-12(M1E)</td><td>PR</td></tr> <tr><td>296483</td><td>WELL</td><td>PR</td><td>10/21/2008</td><td>GW</td><td>045-16052</td><td>JUNIPER 12-4A(M1E)</td><td>PR</td></tr> <tr><td>296484</td><td>WELL</td><td>PR</td><td>10/30/2008</td><td>GW</td><td>045-16053</td><td>JUNIPER 11-1A (M1E)</td><td>PR</td></tr> <tr><td>296609</td><td>WELL</td><td>PR</td><td>10/19/2008</td><td>GW</td><td>045-16088</td><td>JUNIPER 2-9A (M1E)</td><td>SI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	285781	WELL	PR	01/06/2007	GW	045-12515	JUNIPER 1-13A (M1E)	PR	285875	WELL	PR	12/27/2006	GW	045-12582	JUNIPER 2-16A (M1E)	PR	285876	WELL	PR	12/30/2006	GW	045-12581	JUNIPER 2-16 (M1E)	PR	285877	WELL	PR	12/19/2006	GW	045-12580	JUNIPER 1-13 (M1E)	PR	296480	WELL	PR	10/23/2008	GW	045-16049	JUNIPER 1-12A (M1E)	PR	296481	WELL	PR	10/09/2008	GW	045-16050	JUNIPER 2-9(M1E)	PR	296482	WELL	PR	10/19/2008	GW	045-16051	JUNIPER 1-12(M1E)	PR	296483	WELL	PR	10/21/2008	GW	045-16052	JUNIPER 12-4A(M1E)	PR	296484	WELL	PR	10/30/2008	GW	045-16053	JUNIPER 11-1A (M1E)	PR	296609	WELL	PR	10/19/2008	GW	045-16088	JUNIPER 2-9A (M1E)	SI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																				
285781	WELL	PR	01/06/2007	GW	045-12515	JUNIPER 1-13A (M1E)	PR																																																																																				
285875	WELL	PR	12/27/2006	GW	045-12582	JUNIPER 2-16A (M1E)	PR																																																																																				
285876	WELL	PR	12/30/2006	GW	045-12581	JUNIPER 2-16 (M1E)	PR																																																																																				
285877	WELL	PR	12/19/2006	GW	045-12580	JUNIPER 1-13 (M1E)	PR																																																																																				
296480	WELL	PR	10/23/2008	GW	045-16049	JUNIPER 1-12A (M1E)	PR																																																																																				
296481	WELL	PR	10/09/2008	GW	045-16050	JUNIPER 2-9(M1E)	PR																																																																																				
296482	WELL	PR	10/19/2008	GW	045-16051	JUNIPER 1-12(M1E)	PR																																																																																				
296483	WELL	PR	10/21/2008	GW	045-16052	JUNIPER 12-4A(M1E)	PR																																																																																				
296484	WELL	PR	10/30/2008	GW	045-16053	JUNIPER 11-1A (M1E)	PR																																																																																				
296609	WELL	PR	10/19/2008	GW	045-16088	JUNIPER 2-9A (M1E)	SI																																																																																				

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285781	WELL	PR	01/06/2007	GW	045-12515	JUNIPER 1-13A (M1E)	PR
285875	WELL	PR	12/27/2006	GW	045-12582	JUNIPER 2-16A (M1E)	PR
285876	WELL	PR	12/30/2006	GW	045-12581	JUNIPER 2-16 (M1E)	PR
285877	WELL	PR	12/19/2006	GW	045-12580	JUNIPER 1-13 (M1E)	PR
296480	WELL	PR	10/23/2008	GW	045-16049	JUNIPER 1-12A (M1E)	PR
296481	WELL	PR	10/09/2008	GW	045-16050	JUNIPER 2-9(M1E)	PR
296482	WELL	PR	10/19/2008	GW	045-16051	JUNIPER 1-12(M1E)	PR
296483	WELL	PR	10/21/2008	GW	045-16052	JUNIPER 12-4A(M1E)	PR
296484	WELL	PR	10/30/2008	GW	045-16053	JUNIPER 11-1A (M1E)	PR
296609	WELL	PR	10/19/2008	GW	045-16088	JUNIPER 2-9A (M1E)	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1522-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	At wellhead, hooked up to well API # 05-045-12515 Bradenhead				
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	OTHER	STEEL AST		,	
Comment: In same berm as 3 condensate tanks						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity) 500gal						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.472009,-107.622650	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Insufficient	Base Insufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	500 BBLs	STEEL AST		39.472133,-107.622694	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						

Inspector Name: Murray, Richard

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	285781	Type:	WELL	API Number:	045-12515	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift, Bradenhead hooked up to flat tank								
Corrective Action:						Date:			
Facility ID:	285875	Type:	WELL	API Number:	045-12582	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	285876	Type:	WELL	API Number:	045-12581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	285877	Type:	WELL	API Number:	045-12580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	296480	Type:	WELL	API Number:	045-16049	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	296481	Type:	WELL	API Number:	045-16050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	296482	Type:	WELL	API Number:	045-16051	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	296483	Type:	WELL	API Number:	045-16052	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Facility ID: 296484	Type: WELL	API Number: 045-16053	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger Lift](#)

Corrective Action:

Date:

Facility ID: 296609	Type: WELL	API Number: 045-16088	Status: PR	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

Idle WellPurpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: _____

Comment: [Last production numbers posted Sept 2016](#)

Corrective Action:

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Seeding	Pass					
		Ditches	Pass			
Sediment Traps	Pass					
Ditches	Pass					
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802746	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4018002