

API # 123-09226, BRADENHEAD IS NOT PLUMED TO SURFACE FOR PRESSURE MONITORING.

