



photo 1: Facing northwest toward the location.



photo 2: View of vegetation growth at the southeast side of the location. There is little to no vegetation growth in this area.



photo 3: View of groundcover at the south side of the location. The dried up vegetation is Cheatgrass (list c noxious weed).



photo 4: Facing west along the south side of the location (fill slope).



photo 5: Facing west along the south side of the location (fill slope). Vegetation has not adequately established.



photo 6: There is trash debris in a pile at the northwest side of the location.



photo 7: Northwest side of the location facing east toward the cut slope.



photo 8: There is plastic debris along areas of the cut slope.