

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2016

Submitted Date:

12/07/2016

Document Number:

666802772

### FIELD INSPECTION FORM

Loc ID 334770 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
 Name of Operator: ENCANA OIL & GAS (USA) INC  
 Address: 370 17TH ST STE 1700  
 City: DENVER State: CO Zip: 80202-

**Findings:**

- 5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211587	WELL	PR	10/01/2003	GW	045-07348	SHIDELER 20-5	PR
281193	WELL	PR	06/30/2006	GW	045-11412	SHIDELER FEDERAL 20-3 (E20E)	PR
281194	WELL	PR	06/28/2006	GW	045-11413	SHIDELER FEDERAL 20-4 (E20E)	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1117-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Gas Meter Run		# 1		
Comment:	<input type="text"/>			
Corrective Action:			Date:	
Vertical Heated Separator		# 3		
Comment:	<input type="text"/>			
Corrective Action:			Date:	
Plunger Lift		# 3		
Comment:	<input type="text"/>			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.434371,-107.699041
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>211587</u>	Type: <u>WELL</u>	API Number: <u>045-07348</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Plunger Lift</u>		
Corrective Action:		Date:	
Facility ID: <u>281193</u>	Type: <u>WELL</u>	API Number: <u>045-11412</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Plunger Lift</u>		
Corrective Action:		Date:	
Facility ID: <u>281194</u>	Type: <u>WELL</u>	API Number: <u>045-11413</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Plunger Lift</u>		
Corrective Action:		Date:	

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Gravel	Pass			
Rip Rap	Pass					
		Culverts	Pass			
Gravel	Pass					
Sediment Traps	Pass					
Ditches	Pass					
Seeding	Pass					
Retention Ponds	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT