



Photo#1: Overview of Location to SW.

November 16, 2016

Inspection Photos: Laramie Cascade Creek Loc#335803



Photo2: Overview of Location to North.

November 16, 2016

Inspection Photos: Laramie Cascade Creek Loc#335803



Photo#3: Lower Bench below East side of Location.

November 16, 2016

Inspection Photos: Laramie Cascade Creek Loc#335803



Photo#4: Upper Level of Location Housing Separator.

November 16, 2016

Inspection Photos: Laramie Cascade Creek Loc#335803

Photos# 5& 6:

Sparse Vegetation on Areas of Compacted Pad Surface.



November 16, 2016

Inspection Photos: Laramie Cascade Creek Loc#335803