

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2016

Submitted Date:

12/02/2016

Document Number:

681901823**FIELD INSPECTION FORM**

Loc ID 305447	Inspector Name: HELGELAND, GARY	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED																																																																																																																															
2A Doc Num: _____			<b>Findings:</b> 31 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>10633</u> Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u> Address: <u>370 17TH STREET #2170</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																																		
<b>Contact Information:</b> <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>Cogcc.inspections@crestone pr.com</td> <td>ALL INSPECTIONS</td> </tr> </table>				Contact Name	Phone	Email	Comment	,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS																																																																																																																							
Contact Name	Phone	Email		Comment																																																																																																																														
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS																																																																																																																															
<b>Inspected Facilities:</b> <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>434333</td><td>WELL</td><td>DG</td><td>10/17/2016</td><td>LO</td><td>123-38104</td><td>Woolley Sosa 2A-7H-E168</td><td>DG</td></tr> <tr><td>434334</td><td>WELL</td><td>DG</td><td>11/03/2016</td><td>LO</td><td>123-38105</td><td>Woolley Becky 2F-7H-E168</td><td>DG</td></tr> <tr><td>434335</td><td>WELL</td><td>DG</td><td>10/23/2016</td><td>LO</td><td>123-38106</td><td>Woolley Sosa 2D-7H-E168</td><td>DG</td></tr> <tr><td>434336</td><td>WELL</td><td>DG</td><td>11/01/2016</td><td>LO</td><td>123-38107</td><td>Woolley Becky 2D-7H-E168</td><td>DG</td></tr> <tr><td>434337</td><td>WELL</td><td>DG</td><td>10/18/2016</td><td>LO</td><td>123-38108</td><td>Woolley Sosa 2B-7H-E168</td><td>DG</td></tr> <tr><td>434338</td><td>WELL</td><td>DG</td><td>10/30/2016</td><td>LO</td><td>123-38109</td><td>Woolley Becky 2B-7H-E168</td><td>DG</td></tr> <tr><td>434339</td><td>WELL</td><td>DG</td><td>10/24/2016</td><td>LO</td><td>123-38110</td><td>Woolley Sosa 2E-7H-E168</td><td>DG</td></tr> <tr><td>434340</td><td>WELL</td><td>DG</td><td>10/29/2016</td><td>LO</td><td>123-38111</td><td>Woolley Becky 2A-7H-E168</td><td>DG</td></tr> <tr><td>434341</td><td>WELL</td><td>DG</td><td>11/02/2016</td><td>LO</td><td>123-38112</td><td>Woolley Becky 2E-7H-E168</td><td>DG</td></tr> <tr><td>434342</td><td>WELL</td><td>DG</td><td>10/26/2016</td><td>LO</td><td>123-38113</td><td>Woolley Sosa 2F-7H-E168</td><td>DG</td></tr> <tr><td>434343</td><td>WELL</td><td>DG</td><td>11/05/2016</td><td>LO</td><td>123-38114</td><td>Woolley Becky 2H-7H-E168</td><td>DG</td></tr> <tr><td>436731</td><td>WELL</td><td>DG</td><td>10/31/2016</td><td>LO</td><td>123-39241</td><td>Woolley Becky 2C-7H-E168</td><td>DG</td></tr> <tr><td>436733</td><td>WELL</td><td>DG</td><td>11/04/2016</td><td>LO</td><td>123-39242</td><td>Woolley Becky 2G-7H-E168</td><td>DG</td></tr> <tr><td>436738</td><td>WELL</td><td>DG</td><td>10/19/2016</td><td>LO</td><td>123-39245</td><td>Woolley Sosa 2C-7H-E168</td><td>DG</td></tr> <tr><td>436739</td><td>WELL</td><td>DG</td><td>10/30/2016</td><td>LO</td><td>123-39246</td><td>Woolley Sosa 2G-7H-E168</td><td>DG</td></tr> </tbody> </table>			Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG	434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG	434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG	434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG	434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG	434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG	434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG	434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG	434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG	434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG	434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG	436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG	436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG	436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG	436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																											
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG																																																																																																																											
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG																																																																																																																											
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG																																																																																																																											
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG																																																																																																																											
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG																																																																																																																											
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG																																																																																																																											
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG																																																																																																																											
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG																																																																																																																											
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG																																																																																																																											
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG																																																																																																																											
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG																																																																																																																											
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG																																																																																																																											
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG																																																																																																																											
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG																																																																																																																											
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG																																																																																																																											
<b>General Comment:</b> <div style="height: 150px; border: 1px solid black;"></div>																																																																																																																																		

**Inspected Facilities**

Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing set and cemented. Rig on location to drill long string.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing set and cemented. Rig on location to drill long string.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434335 Type: WELL API Number: 123-38106 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434336 Type: WELL API Number: 123-38107 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434337 Type: WELL API Number: 123-38108 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434338 Type: WELL API Number: 123-38109 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: Ensign 140 Pusher/Rig Manager: Robert Escojeda

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: YESPressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES**Drill Fluids****Management:**Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_Multi-Well: YES Disposal Location: \_\_\_\_\_Comment: Ensign Rig #140 on location to drill long string. Derrick screened for fugitive light mitigation. Sound mitigation in place. Chemicals properly stored. BMPs in place. No conditions observed that exceed COGCC rules.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434339 Type: WELL API Number: 123-38110 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing set and cemented. Rig on location to drill long string.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434340 Type: WELL API Number: 123-38111 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434341 Type: WELL API Number: 123-38112 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434342 Type: WELL API Number: 123-38113 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434343 Type: WELL API Number: 123-38114 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing set and cemented. Rig on location to drill long string.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 436731 Type: WELL API Number: 123-39241 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing set and cemented. Rig on location to drill long string.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 436733 Type: WELL API Number: 123-39242 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 436738 Type: WELL API Number: 123-39245 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 436739 Type: WELL API Number: 123-39246 Status: DG Insp. Status: DG**Well Drilling****Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: [Surface casing set and cemented. Rig on location to drill long string.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: [No Bradenhead.](#)

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901823	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017916</a>