

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

675203676**FIELD INSPECTION FORM**
 Loc ID 334724 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Terra, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210762	WELL	PR	11/01/1984	GW	045-06520	HOOAGLUND W-25-2	PR
210951	WELL	PR	11/10/1990	GW	045-06709	HOAGLUND GV 65-2	PR
283974	WELL	PR	03/23/2006	GW	045-12049	HOAGLUND PA 411-2	PR
283975	WELL	PR	03/23/2006	GW	045-12050	HOAGLUND PA 511-2	PR
283976	WELL	PR	03/23/2006	GW	045-12051	HOAGLUND PA 311-2	PR
283977	WELL	PR	03/23/2006	GW	045-12052	HOAGLUND PA 12-2	PR
283978	WELL	PR	03/23/2006	GW	045-12053	HOAGLUND PA 312-2	PR
283979	WELL	PR	03/23/2006	GW	045-12054	HOAGLUND PA 412-2	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:



Inspected Facilities				
Facility ID: <u>210762</u>	Type: <u>WELL</u>	API Number: <u>045-06520</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>210951</u>	Type: <u>WELL</u>	API Number: <u>045-06709</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283974</u>	Type: <u>WELL</u>	API Number: <u>045-12049</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283975</u>	Type: <u>WELL</u>	API Number: <u>045-12050</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283976</u>	Type: <u>WELL</u>	API Number: <u>045-12051</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283977</u>	Type: <u>WELL</u>	API Number: <u>045-12052</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283978</u>	Type: <u>WELL</u>	API Number: <u>045-12053</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283979</u>	Type: <u>WELL</u>	API Number: <u>045-12054</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT