

Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Petro-Canada #72085

Location ID: 311698

Adams County, CO

NESW Section 13 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of GPS verifying location.



2016/12/13 11:03

N39.787885 W103.937383

Figure 2: Photo taken within the drainage, adjacent to the pit location, facing east. Photo shows areas of degradation. See photos from inspection doc. # 682500927 for additional details.



2016/12/13 11:03

N39.787890 W103.937382

Figure 3: Photo taken within the drainage, adjacent to the pit location, facing north. Photo shows areas of degradation. See photos from inspection doc. # 682500927 for additional details.



2016/12/13 11:03

N39.787892 W103.937382

Figure 4: Photo taken within the drainage, adjacent to the pit location, facing northwest. Photo shows areas of degradation. See photos from inspection doc. # 682500927 for additional details.



2016/12/13 11:04

N39.788033 W103.938268

Figure 5: Photo taken within the drainage, adjacent to the pit location, facing east. Photo shows areas of degradation. See photos from inspection doc. # 682500927 for additional details.