

Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Kaiser-Francis Oil Co # 45898

Location ID: 376749

Adams County, CO

SENW Section 25 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



2016/12/13 11:56

N39.763172 W103.937062

Figure 1: Photo of GPS verifying location.



2016/12/13 11:56

N39.763198 W103.937078

Figure 2: Photo taken from the south end of the location, facing northeast. Photo shows location has not achieved uniform vegetative cover.



2016/12/13 11:57

N39.763197 W103.937077

Figure 3: Photo taken from the south end of the location, facing north. Photo shows location has not achieved uniform vegetative cover.



2016/12/13 11:57

N39.763197 W103.937077

Figure 4: Photo taken from the south end of the location, facing northwest. Photo shows location has not achieved uniform vegetative cover.



2016/12/13 11:57

N39.763230 W103.937310

Figure 5: Photo taken from the west end of the location. Photo shows equipment remaining on the location.



2016/12/13 11:57

N39.763230 W103.937295

Figure 6: Photo taken from the location, facing north. Photo shows scotch thistle stalks from this years growth on location. This is a Colorado State, and Adams County noxious weed and needs to be managed and removed.



2016/12/13 12:00

N39.764110 W103.936940

Figure 7: Photo taken from the northeast end of the location, facing south. Photo shows erosion leading off of the well location.



2016/12/13 12:01

N39.763513 W103.936735

Figure 8: Photo taken from the southeast end of the well location, facing southeast. Photo shows location has not been adequately recontoured and is experiencing degradation due to stormwater erosion.



Figure 9: Photo taken from the access road, on the south end of the location. Photo shows equipment remaining.