

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2016

Submitted Date:

12/08/2016

Document Number:

685501585**FIELD INSPECTION FORM**

Loc ID 418198 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 418194 | WELL | PR | 12/27/2011 | OW | 123-31850 | CODY D 3-20 | SI |
| 420353 | WELL | PR | 07/15/2011 | OW | 123-32555 | BECCA D 03-32D | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | NEED WELLHEA SIGN BECCA3-32D | | |
| Corrective Action: | Install sign to comply with Rule 210.a. | Date: | 01/05/2017 |

Emergency Contact Number:

| | | |
|--------------------|----|-------------|
| Comment: | OK | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | ROD IRON FENCES ON WELLHEADS SE CORNER N40.15254 W-104.32515 | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | BARBWIRE FENCE | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | SE CRONER N40.15206 W-104.32436 | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | SE CRONER N40.15206 W-104.32436 | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 2 | | |

| | | | |
|--------------------|---------------------------------------|-------|--|
| Comment: | SE CORNER N40.15206 W-104.32436 | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--------------------------------|-----------|---------------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | <100 BBLS | CONCRETE SUMP/VAULT | | , | |
| Comment: | CONCRETE VAULT 60 BBL CAPACITY | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLS | Open Top | | 40.151920,-104.324350 |
| Comment: | | | | | |
| Corrective Action: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

Flaring:

| | | |
|----------|-------------------|--|
| Type | Ignitor/Combustor | |
| Comment: | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Inspected FacilitiesFacility ID: 418194 Type: WELL API Number: 123-31850 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____Facility ID: 420353 Type: WELL API Number: 123-32555 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND, IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND, IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|------------------------------------|----------|------------|
| INTERMITTER CONTROLLER ON WELLHEAD | montoyaj | 12/08/2016 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 685501585 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027983 |
| 685501586 | NEED WELL SIGN BECCA 3-32 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4022641 |