

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2016

Submitted Date:

12/08/2016

Document Number:

680101343**FIELD INSPECTION FORM**
 Loc ID 335902 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 66571Name of Operator: OXY USA WTP LPAddress: P O BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Sinard, Karen		karen_sinard@oxy.com	
Lutz, Debbie		debbie.lutz@state.co.us	
Ramos, Martha		martha.ramos@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285254	WELL	AL	12/10/2009	LO	045-12408	CASCADE CREEK 697-4-54D	RI
285255	WELL	AL	12/10/2009	LO	045-12405	CASCADE CREEK 697-3-41D	RI
285256	WELL	AL	12/10/2009	LO	045-12406	CASCADE CREEK 697-4-29D	RI
285257	WELL	AL	12/10/2009	LO	045-12407	CASCADE CREEK 697-4-39D	RI
285258	WELL	AL	12/10/2009	LO	045-12404	CASCADE CREEK 697-3-25D	RI

**General Comment:**

This is an Abandoned Location Inspection, Bond Release Related for Five Wells listed in Related Facilities, below; on Loc#335902; APDs First Approved 6/19/2006; Permits Abandoned 12/3/2009. It does not appear that these AL Wells were drilled on Location which Houses Active Pit/Pond Fac#291970; therefore these are Well Releases on an Active Location.



Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Comment:

1002a. FENCING

Comment

Corrective Action		Date
-------------------	--	------

Comment

Corrective Action	Date

## 1002c. PROTECTION OF SOILS

Comment

Corrective Action	Date

## 1002E. SURFACE DISTURBANCE MINIMIZATION

Comment

Corrective Action	Date

1003a. Waste and Debris removed?

Comment

Corrective Action	Date

Unused or unneeded equipment onsite?

Comment

Corrective Action	Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action	Date

Guy line anchors marked?

Comment

Corrective Action	Date

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: [There is no Evidence of the Five AL Wells on this Active Location.](#)

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Pass \_\_\_\_\_ Well Release on Active Location ☒ Multi-Well Location ☒

Document Num	Description	URL
680101343	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024881</a>
680101344	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4024589</a>