



**photo 1:** Center of the location facing north.



**photo 2:** Center of the location facing west.



**photo 3:** Center of the location facing south.



**photo 4:** Center of the location facing east.



**photo 5:** The soils seemed compacted in areas of the location which may be impacting vegetation establishment.



**photo 6:** A utility box remains at the center of the location.



**photo 7:** View of vegetation growth.



**photo 8:** There is undesirable weed growth (Russian thistle) throughout the location.



**photo 9:** There is an area at the west side of the location where desirable vegetation is establishing well.



**photo 10:** Facing south toward the surrounding undisturbed pasture.