

Final Reclamation & Stormwater Inspection

12/13/2016

Operator: Latham Expl Co Inc. #50275

Location ID: 376690

Adams County, CO

NENE Section 36 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources




Figure 1: Photo of GPS verifying location.



2016/12/13 12:40

N39.753287 W103.928455

Figure 2: Photo taken from the north end of the location, facing southwest. Photo shows location has not achieved uniform vegetative cover.



2016/12/13 12:40

N39.753277 W103.928447

Figure 3: Photo taken from the north end of the location, facing south. Photo shows location has not achieved uniform vegetative cover.



2016/12/13 12:41

N39.753042 W103.928763

Figure 4: Photo taken from the location. Photo shows pipe debris remaining on location.



2016/12/13 12:42

N39.752560 W103.928590

Figure 5: Photo taken from the south end of the location. Photo shows equipment remains on location.



2016/12/13 12:43

N39.752153 W103.928857

Figure 6: Photo taken from the south end of the location. Photo shows debris remaining on location.



2016/12/13 12:44

N39.752333 W103.929198

Figure 7: Photo taken from the west end of the location. Photo shows exposed pipe remaining in the ground



2016/12/13 12:44

N39.752340 W103.929168

Figure 8: Photo taken from the west end of the location. Photo shows exposed pipe remaining in the ground