

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2016

Submitted Date:

12/16/2016

Document Number:

675203700**FIELD INSPECTION FORM**
 Loc ID 334663 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271021	WELL	PR	06/06/2012	GW	045-09813	S.PARACHUTE FEDERAL 30-14	PR
278446	WELL	PR	06/06/2012	GW	045-10882	FEDERAL 30-1BB (PA30)	PR
284146	WELL	PR	06/06/2012	GW	045-12095	FEDERAL 20-13 (PA30)	PR
423625	WELL	PR	02/13/2012	GW	045-20780	Federal 29-4 (PA-30)	PR
423631	WELL	PR	02/13/2012	GW	045-20781	Federal Smith 30-2 (PA-30)	PR
423632	WELL	PR	02/13/2012	GW	045-20782	Federal Smith 19-15 (PA-30)	PR
423634	WELL	PR	02/13/2012	GW	045-20783	Federal 29-4BB (PA-30)	PR
423635	WELL	PR	02/13/2012	GW	045-20784	Federal 29-4C (PA-30)	PR
423636	WELL	PR	02/13/2012	GW	045-20785	Federal 20-13A (PA-30)	PR
423637	WELL	PR	02/28/2012	GW	045-20786	Federal 29-4A (PA-30)	PR
423641	WELL	PR	02/15/2012	GW	045-20787	Federal 19-16BB (PA-30)	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:		Federal tanks			
Corrective Action:				Date:	

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	<u>271021</u>	Type:	<u>WELL</u>	API Number: <u>045-09813</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>278446</u>	Type:	<u>WELL</u>	API Number: <u>045-10882</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>284146</u>	Type:	<u>WELL</u>	API Number: <u>045-12095</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423625</u>	Type:	<u>WELL</u>	API Number: <u>045-20780</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423631</u>	Type:	<u>WELL</u>	API Number: <u>045-20781</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423632</u>	Type:	<u>WELL</u>	API Number: <u>045-20782</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423634</u>	Type:	<u>WELL</u>	API Number: <u>045-20783</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423635</u>	Type:	<u>WELL</u>	API Number: <u>045-20784</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423636</u>	Type:	<u>WELL</u>	API Number: <u>045-20785</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423637</u>	Type:	<u>WELL</u>	API Number: <u>045-20786</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>423641</u>	Type:	<u>WELL</u>	API Number: <u>045-20787</u> Status: <u>PR</u> Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT