

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/19/2016
Submitted Date:
12/19/2016
Document Number:
674703461

FIELD INSPECTION FORM

Loc ID 335598 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

25 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284957	WELL	PR	06/05/2006	GW	045-12325	N PARACHUTE MF10C N04 696	PR
284958	WELL	PR	02/01/2014	GW	045-12324	N PARACHUTE MF11D N04 696	PR
284959	WELL	PR	06/05/2006	GW	045-12323	N PARACHUTE WF17A N04 696	PR
284960	WELL	PR	06/05/2006	GW	045-12322	N PARACHUTE MF16C N04 696	PR
284961	WELL	PR	01/08/2007	GW	045-12321	N PARACHUTE MF09C N04 696	PR
284962	WELL	PR	06/05/2006	GW	045-12320	N PARACHUTE MF16A N04 696	PR
284963	WELL	PR	01/01/2010	GW	045-12319	N. PARACHUTE MF12D N04 696	PR
284964	WELL	PR	06/05/2006	GW	045-12318	N PARACHUTE MF09A N04 696	PR
284965	WELL	PR	01/01/2010	GW	045-12317	N.PARACHUTE MF 18C N04 696	PR
284966	WELL	PR	06/05/2006	GW	045-12316	N PARACHUTE MF15C N04 696	PR
284967	WELL	PR	06/05/2006	GW	045-12315	N PARACHUTE MF17C N04 696	PR
284968	WELL	PR	06/05/2006	GW	045-12314	N PARACHUTE MF18A N04 696	PR
300233	WELL	PR	12/05/2009	GW	045-17863	N. PARACHUTE MF10A-4 N04 696	PR
300234	WELL	PR	01/14/2010	GW	045-17862	N.PARACHUTE MF 18A-4 N04 69	PR
300235	WELL	PR	12/30/2009	GW	045-17861	N.PARACHUTE MF10C-4 M04 696	PR
300236	WELL	PR	12/30/2009	GW	045-17860	N. PARACHUTE MF11A-4 N04 696	PR

300237	WELL	PR	02/10/2011	GW	045-17859	N.PARACHUTE MF06D-4 N04 696	PR
301809	WELL	PR	12/30/2009	GW	045-18279	N. PARACHUTE MF15B-4 N04 696	PR
301810	WELL	PR	12/30/2009	GW	045-18280	N. PARACHUTE MF07B-4 N04 696	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Snow cover		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	800-791-7691		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 19		
Comment:	seils		
Corrective Action:			Date:
Type: Gas Meter Run	# 19		
Comment:	Gas lift		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	chemical containers		
Corrective Action:			Date:
Type: Plunger Lift	# 19		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284957	Type:	WELL	API Number:	045-12325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284958	Type:	WELL	API Number:	045-12324	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284959	Type:	WELL	API Number:	045-12323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284960	Type:	WELL	API Number:	045-12322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284961	Type:	WELL	API Number:	045-12321	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284962	Type:	WELL	API Number:	045-12320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284963	Type:	WELL	API Number:	045-12319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284964	Type:	WELL	API Number:	045-12318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

Facility ID:	284965	Type:	WELL	API Number:	045-12317	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284966	Type:	WELL	API Number:	045-12316	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284967	Type:	WELL	API Number:	045-12315	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	284968	Type:	WELL	API Number:	045-12314	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	300233	Type:	WELL	API Number:	045-17863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	300234	Type:	WELL	API Number:	045-17862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	300235	Type:	WELL	API Number:	045-17861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	300236	Type:	WELL	API Number:	045-17860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

Facility ID: <u>300237</u>	Type: <u>WELL</u>	API Number: <u>045-17859</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: <u>Producing well</u>				
Corrective Action:			Date:	

Facility ID: <u>301809</u>	Type: <u>WELL</u>	API Number: <u>045-18279</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: <u>Producing well</u>				
Corrective Action:			Date:	

Facility ID: <u>301810</u>	Type: <u>WELL</u>	API Number: <u>045-18280</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Producing Well

Comment: <u>Producing well</u>				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
Check Dams	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT