

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2016

Submitted Date:

12/14/2016

Document Number:

681901859**FIELD INSPECTION FORM**
 Loc ID 305447 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**32 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG

**General Comment:**

Ensign Rig # 140 on location to drill wells to TD. Drilling on Woolley Becky 2C

**Inspected Facilities**Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434335 Type: WELL API Number: 123-38106 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Ensign # 140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: [Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434336 Type: WELL API Number: 123-38107 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: [Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [No Bradenhead.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434337 Type: WELL API Number: 123-38108 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: [Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434338 Type: WELL API Number: 123-38109 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon

Permit Posted: \_\_\_\_\_

Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONSComment: Surface casing and production casing set and cemented. Well drilled to TD.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434339 Type: WELL API Number: 123-38110 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon

Permit Posted: \_\_\_\_\_

Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONSComment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434340 Type: WELL API Number: 123-38111 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon

Permit Posted: \_\_\_\_\_

Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: Surface casing and production casing set and cemented. Well drilled to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434341 Type: WELL API Number: 123-38112 Status: DG Insp. Status: DG

**Well Drilling****Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B Moon

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_

Multi-Well: YES Disposal Location: WASTE CONNECTIONS

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434342 Type: WELL API Number: 123-38113 Status: DG Insp. Status: DG

**Well Drilling****Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434343 Type: WELL API Number: 123-38114 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 436731 Type: WELL API Number: 123-39241 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: WASTE CONNECTIONS

Comment: Ensign Rig #140 on location. Derrick screened for fugitive light mitigation. Sound mitigation in place. Chemicals properly stored. BOPs tested. Vehicle tracking pad in use. No conditions observed that exceed COGCC rules at time of inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 436733 Type: WELL API Number: 123-39242 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTION

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 436738 Type: WELL API Number: 123-39245 Status: DG Insp. Status: DG

**Well Drilling**

Rig: Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: No Bradenhead.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 436739 Type: WELL API Number: 123-39246 Status: DG Insp. Status: DG

**Well Drilling**

Rig: Rig Name: Ensign Rig #140 Pusher/Rig Manager: B. Moon  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: 5000 Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: WASTE CONNECTIONS

Comment: Surface casing set and cemented. Ensign Rig # 140 on location to drill to TD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

BradenHead	
Comment:	<div>No Bradenhead.</div>
Corrective Action:	<div></div>
	Date: <div></div>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Covering Materials	Pass	
				Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901859	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4033472</a>