

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	WEEDS		
Comment:	See attached photos.		
Corrective Action:	Control weeds at tank battery.	Date:	<u>01/04/2017</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Vertical Heater Treater	# 1		corrective date
Comment:	valve leak, solar panel, shed, berms, GPS 39.61491, -104.32372		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	on VHT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	solar panel and radio telemetry, GPS 39.61494, -104.32372, 16.8 psi-flowline, 0 flow		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.614530,-104.323750
Comment:					
Corrective Action:					Date:
Paint					
Condition:					
Other (Content):					
Other (Capacity):					
Other (Type):					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:					
Corrective Action: Maintain crude oil tank berms.					Date: <u>01/11/2017</u>
Venting:					
Yes/No:					
Comment:					
Corrective Action:					Date:
Flaring:					
Type:					
Comment:					
Corrective Action:					Date:

Location Construction

Location ID: 204791 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 204791 Type: WELL API Number: 005-06876 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
This was an inspection of the tank battery only.	ShermaSe	12/21/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673714560	Overland State-Craig 3-16 Tank Battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4034863