



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Interim reclamation areas are revegetating with desirable species such as western wheatgrass (*Pascopyrum smithii*), false goldenaster (*Heterotheca villosa*), and dropseed (*Sporobolus* sp.).





Photo 3. View of the western portion of the project area from the southwestern corner facing northward.





Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 5. View of the eastern portion of the project area from the southeastern corner facing northward.





Photo 6. View of erosional channel forming in the southern portion of the project area.





Photo 7. View of stormwater run on in the northern portion of the project area.